# Oil Field Environmental Incident Summary

Responsible Party: Oxy USA Inc Well Operator: OXY USA INC. Well Name: MARTIN 4-30-31H-144-96

Field Name: CABERNET Well File #: 25709

Date Incident:11/25/2013Time Incident:1230Facility ID Number:County:DUNNTwp:144Rng:96Sec:30Qtr:

Location Description: A 30 ft X 18 ft area adjacent to the well pad was misted with condensate from

a production flare.

Submitted By: Dustin Tescher Received By:

Contact Person: Terry Ryland

5 GREENWAY PLAZA STE 110 HOUSTON, TX 77046-0506

General Land Use: Pasture Affected Medium: Topsoil

Distance Nearest Occupied Building:0.75 MilesDistance Nearest Water Well:0.75 Miles

Type of Incident: Treater Popoff

Release Contained in Dike: No Reported to NRC: No Spilled Units Recovered Units Followup Units

	Spilled	Units	Recovered	Units	
Oil	0	barrels	0	barrels	
Brine	0	barrels	0	barrels	
Other	5	gallons	0	gallons	

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: 1/5/2016 Clean Up Concluded: 3/31/2014

Risk Evaluation:

flammable material on the ground outside of location., danger of grass fire

Areal Extent:

30ft x 18ft

0

gallons

## Potential Environmental Impacts:

All released fluids that went off location was burned off so risk of contamination is minimal.

#### Action Taken or Planned:

The well was shut down to stop the release and the gas line regulator will be unfrozed before operatiosn resume. The fire extinguished by itself and a crew was stationed close by to ensure it does not reignite.

Wastes Disposal Location:

Agencies Involved:

## **Updates**

Date: 11/26/2013 Status: Reviewed - Follow-up Required Author: Roberts, Kris

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Release from treater sprayed off location. Followup is necessary.

Date: 12/3/2013 Status: Inspection Author: O'Gorman, Brian

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

## Notes:

Arrived on location 12/3/13 at 10:15 CT. Observed the area and took photographs. The  $18 \times 30$  foot area adjacent to and east of the well pad showed signs of the vegetation being burned with no residual oil mist in and around the incident area. Area appeared to be free of product after the burning. No further followup necessary.